


ST JOHN'S WILLIS ORGAN RESTORATION 2004-5

PHOTO DIARY (2)



On Ascension day - 20th May 2004, one of the smaller bellows was removed from the interior of the organ. Weighing over 300 lbs, it was a job for four men, working very carefully, to avoid damaging other smaller components.

The man in the blue shirt is David Wells, the organ builder whose company is doing the restoration work

Here's a view of interior ducting components exposed by the removal of many ranks of organ pipes, both great and small.



The St John Priory chapel has been fenced off temporarily to provide a holding area for ranks of pipes waiting to be wrapped and boxed up for safe transport to Liverpool.

