

## PHOTO DIARY (6)


**LATE SEPTEMBER 2004**

### RARE SIGHTS

At last the stained glass window panels, cleaned and re-leaded, are back in their proper place, and the external wall has been re-plastered.

The photograph is taken from within the empty black painted timber frame of the organ, awaiting the return of thousands of restored parts in the months ahead.

Never before has it been possible to photograph this window, because the organ has enclosed it since 1894. At last the Churchwardens are able to update their inventory !



**Above** are pipes above the organ console, looking out into the choir. Soon these pipes will speak again for the first time in ninety years.

**Opposite** are the 16ft pipes which overlook the south central aisle



### RECONSTRUCTION BEGINS

The first of the wind chests is re-installed, and ranks of pipes at the periphery of the instrument are returned to their places.