


PHOTO DIARY (7)



ON-SITE RESTORATION WORK

The choir becomes a temporary workshop for David Wells and his colleagues.

They are removing dents from pipework above the organ console (a consequence of un-supervised workmen propping ladders against them in times past). This is not just for appearances sake. The restoration will give the pipes on the outer casing their voice once more.

BEFORE AND AFTER

The seven pipes in the middle have been returned to mint condition.

You can see the dents in the others, on the left and the right.

It seems appropriate that the Easter candle is parked next to them!



David Wells, testing a finished pipe



A pipe being reinstated