

ST JOHN'S WILLIS ORGAN RESTORATION 2004-5

PHOTO DIARY (8)

TAKE A GOOD LOOK NOW!

Hopefully, this view of the window in the Alderman's Aisle will not be seen again for another century!

One of the wind-chests is seen here at the bottom of the picture, and behind it, the outer ranks of wooden pipes, returned to their position following the renewal of the wall, and the ducting beneath, which suffered from water penetration, and had to be renewed.



Another view, soon to disappear for a very long time

The first of hundreds of pipes are here returned to their place in the swell organ casing.



Here we see the three restored 'touch boxes' - interface between the keyboard and the wind mechanisms, in their right place once more at the back of the organ console.

Here, the three renovated keyboards are returned to their proper position in the organ console, ready to be re-connected to the 'touch boxes'

